

KENT HOSPITAL WOMEN'S IMAGING CENTER

455 Toll Gate Road
 Warwick, RI 02886
 401-736-1988

✓ = Yes ✗ = No N/A = Not Applicable

ACCESSIBILITY INFORMATION

Building Accessibility

ACCESSIBLE PARKING

Car – ✓Yes

Van – ✗No

ROUTE TO MAIN ENTRANCE FROM PARKING

Curb cuts available – N/A

Clear path with no obstacles – ✓Yes

Route of travel (level or sloped) – Level

Route of travel 36" minimum width – ✓Yes

Ramp – N/A

Handrails 48" maximum height from ground – N/A

Automatic door entry – ✓Yes

Threshold at entry is flat or 1/2" maximum – ✓Yes

Doorway 32" minimum width – ✓Yes

Comment for Route to Main Entrance from Parking: Level path from parking area to curb free access at main entrance.

ELEVATOR ACCESSIBILITY

Mammography Suite on main floor – ✓Yes

➔ Mammography Suite Accessibility

WAITING ROOM ACCESSIBILITY

Entrance door 32" minimum width – ✓Yes

Floor space in seating area for wheelchair – ✓Yes

CHANGING AREA

Dressing room – ✓Yes

Doorway 32" minimum width – ✓Yes

60" turnaround for wheelchair – ✓Yes

Changing bench – ✓Yes

Back support to bench – ✓Yes

Grab bars at bench area – ✗No

Changing area available in Mammography room – ✓Yes

🔗 MAMMOGRAPHY ROOM

Doorway 32" minimum width – ✓Yes

36" clear pathway to mammography machine – ✓Yes

60" turnaround for wheelchair – ✓Yes

Imaging plate lowers to 24" above the floor allowing a person to remain seated in wheelchair – ✓Yes

📍 RESTROOM ACCESSIBILITY

Door 32" minimum width – ✓Yes

Push door or door handles are latch type – ✓Yes

Turnaround 60" minimum in toilet area – ✓Yes

Two grab bars 36" maximum height from floor – ✓Yes

Toilet paper dispenser 19" maximum height from floor – ✓Yes

Hand towel dispenser 48" maximum height from floor – ✓Yes

Sink has 29" minimum space from floor to base – ✓Yes

Sink faucet is lever operated, push, or electronically controlled – ✓Yes

Exposed pipes under the sink are wrapped – ✓Yes