

TOLL GATE RADIOLOGY

300 Toll Gate Road, Suite 101A
 Warwick, RI 02886
 401-738-3100

✓ = Yes ✗ = No N/A = Not Applicable

ACCESSIBILITY INFORMATION

Building Accessibility

ACCESSIBLE PARKING

Car – ✓Yes

Van – ✗No

ROUTE TO MAIN ENTRANCE FROM PARKING

Curb cuts available – ✓Yes

Clear path with no obstacles – ✓Yes

Route of travel (level or sloped) – Level

Route of travel 36" minimum width – ✓Yes

Ramp – N/A

Handrails 48" maximum height from ground – N/A

Automatic door entry – ✗No

Threshold at entry is flat or 1/2" maximum – ✓Yes

Doorway 32" minimum width – ✓Yes

Comment for Route to Main Entrance from Parking: Slight incline at curb cut to sidewalk.

ELEVATOR ACCESSIBILITY

Mammography Suite on main floor – ✓Yes

Mammography Suite Accessibility

WAITING ROOM ACCESSIBILITY

Entrance door 32" minimum width – ✓Yes

Floor space in seating area for wheelchair – ✓Yes

CHANGING AREA

Dressing room – ✓Yes

Doorway 32" minimum width – ✓Yes

60" turnaround for wheelchair – ✗No

Changing bench – ✗No

Back support to bench – ✗No

Grab bars at bench area – ✗No

Changing area available in Mammography room – ✓Yes

MAMMOGRAPHY ROOM

Doorway 32" minimum width – ✓Yes

36" clear pathway to mammography machine – ✓Yes

60" turnaround for wheelchair – ✓Yes

Imaging plate lowers to 24" above the floor allowing a person to remain seated in wheelchair – ✓Yes

RESTROOM ACCESSIBILITY

Door 32" minimum width – ✓Yes

Push door or door handles are latch type – ✗No

Turnaround 60" minimum in toilet area – ✗No

Two grab bars 36" maximum height from floor – ✗No

Toilet paper dispenser 19" maximum height from floor – ✓Yes

Hand towel dispenser 48" maximum height from floor – N/A

Sink has 29" minimum space from floor to base – N/A

Sink faucet is lever operated, push, or electronically controlled – ✓Yes

Exposed pipes under the sink are wrapped – ✗No

Bathroom in hallway has one grab bar but the one in waiting area has none. Paper towels available on counter.